

GEOLOGICAL SURVEY  
**WELL STATUS REPORT**

(To be submitted in quintuplicate on all inactive wells)

NAME AND ADDRESS OF OPERATOR

Martin Yates III- 207 So. 4th Street - Artesia, NM 88210

WELL NO. AND LEASE NAME

2 HEY "A" Federal

LEASE NO.

05020

Section

29

Township

19S

Range

31E

Footage Location of Well:

2310 feet from North line

2310 feet from West line

Pool

Hackberry (Yates S.R.)

COUNTY

Eddy

STATE

NM

1. When Was Well Shut-in or Last Produced?

Prior to July 1972

2. Type Well

☐

Oil Well

☐

Gas Well

☒

Temp. Abd. Well

☐

3. Producing Capability

BOFD

MCFGPD

BWPD

Date Last Tested

4. Is Well Considered Capable of Production in Paying Quantities?

☐

Yes

☒

No

5. If Capable of Producing in Paying Quantities, Give Reasons For Not Producing Well.

6. If Not Capable of Producing in Paying Quantities, Give Reasons For Not Plugging Well At This Time.

Well is in area of improved secondary recovery possibilities, and well has potential for unit participation.

7. What Are Future Plans For Operating Well (Include Estimated Dates)?

Possible unitization within 2-5 years.

**RECEIVED**  
**JUN 18 1976**  
**U. S. GEOLOGICAL SURVEY**  
**ARTESIA, NEW MEXICO**

I hereby certify that the foregoing is true and correct

SIGNED

*Eddie M. Taylor*

TITLE

Engineer

DATE

6-17-76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE