

(SUBMIT IN TRIPLICATE)

Land Office New MexicoLease No. 06309-AUnit 1UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 1, 1963

Runyan Ranch Unit
Well No. 1 is located 660 ft. from [N] line and 910 ft. from [E] line of sec. 12

NE/4 Section 12

(1/4 Sec. and Sec. No.)

T-19-S R-21-E

(Twp.)

(Range)

NMPM

(Meridian)

Wildcat

(Field)

Eddy

(County or Subdivision)

New Mexico

(State or Territory)

RECEIVED

The elevation of the derrick floor above sea level is _____ ft.

OCT 8 1963

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

O. C. C.
ARTESIA, OFFICE

Request authority to change hole size from 8 3/4" to 7 7/8" below
intermediate casing at 1816 feet.

RECEIVED
OCT 7 1963
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tom Brown Drilling Company, Inc.Address % Albritton & MeyerP.O. Box 524, Midland, TexasBy [Signature]Title Agent