

Form 9-831a
(Feb. 1961)Budget Bureau No. 42-R358.4.
Form Approved.

APPROVED
MAY 17 1963
A. R. [Signature]
DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office
Lease No. 011805-1
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

1-17-19.63

Ross Ranch

Well No. 1 is located 660 ft. from N line and 1980 ft. from E line of sec. 20NE NE Sec. 20
(1/4 Sec. and Sec. No.)1-19-6
(Twp.)R-25-E
(Range)N H P M
(Meridian)

(Field)

1963
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 3538 ft. Or.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4-15-63 Pulled 545' of 7" OD 20# J-55 Sals. Casing
Pulled 162' of 8-5/8" OD 24# J-55 Sals. Casing
With all casing out of hole this well was plugged
as follows:
25 sk. plug from 630' to 530'
Heavy drlg. mud from 530' to 20'
10 sk. plug from 20' to surface with marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Hondo Oil & Gas CompanyAddress Box 129Artesia, New MexicoBy Al Deans by L. M. [Signature]Title Dist. Prod. Supt.