

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

L.C.

029387 (o)

Lease No.

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

OCTOBER 30, 19 63

V.S. WELCH KENWOOD ✓

Well No. 2 is located 990 ft. from {N} line and 330 ft. from {E} line of sec. 29

NW NW SEC. 29 18S 31E N.M.P.M.

($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

SHUGART EDDY NEW MEXICO

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

ON AUGUST 18, 1963 RAN 745 FT. OF 8-5/8" CASING AND CEMENTED WITH 50 BAGS. ON OCTOBER 6, 1963 RAN 3868 FT. OF 5" CASING AND CEMENTED WITH 100 BAGS. SHUT DOWN AFTER EACH OPERATION 72 HOURS AND TESTED.....FOUND WATER SHUT OFF COMPLETE.

RECEIVED

OCT 4 1963

G. G. C.
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company V. S. WELCH

P. O. DRAWER #

Address ARTESIA, NEW MEXICO

By

Thomas J. Welch

Title

AGENT