


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office **LAS CRUCES**  
Lease No. **020387 (e)**  
Unit **S**

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 28

19 63

F. S. WELCH KENWOOD

Well No. **I** is located **2310** ft. from **N** line and **350** ft. from **E** line of sec. **20****38 NW SEC. 20****10 S****31 E****N. M. P. M.**

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

**SHUGART**

(Field)

**EDDY**

(County or Subdivision)

**NEW MEXICO**

(State or Territory)

RECEIVED

AUG 27 1963

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

ON APRIL 11, 1963 WE RAN 310 FEET OF 8-5/8" CASING AND  
CEMENTED WITH 75 BAGS. SHUT DOWN 72 HOURS AND TESTED  
WITH COMPLETE SHUTOFF.

RECEIVED  
AUG 14 1963  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **F. S. WELCH**  
**DRAVER #**  
Address **ARTESIA, NEW MEXICO**

By

Title

AGENT