

Form 9-331a
(Feb. 1961)

(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office

L. C.

Lease No.

029387 (b)

Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

MAY 16 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	SANDPRAO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

MAY 8

19 65

I. S. WELCH SHUGART

Well No. **7-D** is located **980** ft. from **N** line and **300** ft. from **E** line of sec. **30**

NW NW SEC. 30

10 S

31 E

N.M.P.M.

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

SHUGART

EDDY

NEW MEXICO

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

ON MARCH 14, 1963 TREATED WITH 85,000# OF SAND AND 1650
 BBL. OF OIL THROUGH PERFORATIONS IN THE 5 1/2" CASING FROM
 3401-3416 AND 3471-3482.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company


I. S. WELCH

Address

P. O. DRAWER #

ARTESIA, NEW MEXICO

By



Title

AGENT