

APPROVED

MAY 13 1964

RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. NM 01167

Unit I

Copy 57.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, New Mexico 12/3, 19 63

Well No. 1 is located 2310 ft. from N line and 660 ft. from E line of sec. 5

NE/4SE/4 5 19 S 31 E NMPM
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Shugart Eddy N. Mex.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3585 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Well and lease designated: Seeley Federal #1.

Subject well was drilled to TD of 3842 and plugging application filed. Application to plug was approved 11/26/63. Plugging of the well was performed in following manner:

30 sx cement plug was set in hole from 3820-3720; 30 sx cement plug was set 3300-3200; 30 sx plug was set 2250-2150; 30 sx cement plug set 930-830; casing shoot-off point was 519' and 30 sx cement plug set at 519-419; 15 sx cement plug was set to surface. All intervals between cement plugs was filled with mud. All equipment has been removed from the location and well location and pits, etc. have been returned to natural surface contour, a suitable marker has been placed for identifying the location and is ready for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company CACTUS DRILLING COMPANY

Address P O Box 1826

Hobbs, New Mexico

MAY 14 1964

O. C. C.
ARTESIA, OFFICE

By [Signature]

Title Production Supt.