

Form 9-331a
(Feb. 1951)**APPROVED**

FEB 20 1963

RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYBudget Bureau No. 42-R358.4.
Form Approved.Land Office **L. C.**
Lease No. **089387 (b)**
Unit **H****SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	1
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

FEBRUARY 1719 **63****V. S. WELCH SHUGART**Well No. **D-4** is located **8310** ft. from **(N)** line and **990** ft. from **(E)** line of sec. **30****SE NE SEC. 30**

(1/4 Sec. and Sec. No.)

16S

(Twp.)

31E

(Range)

N.M.P.M.

(Meridian)

SHUGART

(Field)

EDDY

(County or Subdivision)

NEW MEXICO

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

ON 11/21/62 RAN 768 FT. OF 8-5/8" CASING AND CEMENTED WITH 75 BAGS. SHUT DOWN 72 HOURS AND TESTED WITH COMPLETE SHUTOFF. ON JANUARY 4, 1963 RAN 3819 FT. OF 5 1/2" CASING AND CEMENTED WITH 175 BAGS. SHUT DOWN 72 HOURS AND TESTED. FOUND SHUTOFF COMPLETE.

RECEIVED

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **V. S. WELCH**
DRAVER W
Address **ARTESIA, NEW MEXICO**

By _____

Title **AGENT**