

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4. Form Approved.
Land Office
Lease No. 620387 (A)
Unit C E
An .

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF. SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING. SUBSEQUENT REPORT OF ALTERING CASING.
	NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
		SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

			A	AT Z		19 63		
	7.3.7 Well No.	BLCH 3 LD		? ted 990 ft.	from. N line	e an 2210	ft. from $\{E_{\mathbf{W}}\}$ line	e of sec. 30
I S	II	SEC.	30	I8 S			P. H.	. •
-	SKÜ	Sec. and Sec. N	lo.)	(Twp.)	(Range)	(Merid	ian) KRN MEXIC	o
		(Field)		(C	county or Subdivision)		(State or Territ	

The elevation of the derrick floor above sea level is _____ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

ON I2/I0/62 we had 720 prot of 8-5/8" casing and charten with 75 backs. On 2/I0/63 had 3857 prot of 58" casing and charten with I75 backs. Shut down after zage operation and thereb with complete enutopy.

I understan	d that this plan of work must receive approval in writing by t	he Geological Survey before operations may be commenced.
Company	7. S. WELCH DRIWER W	
		No. 2. 2
Address	ARTESIA, WEN MELICO	$\mathbf{B}_{\mathbf{y}}$
		By COCCOCO
		Title