

Copy to J.
to

DEVIATION REPORT

The following deviations were taken by Sharp Drilling Company while drilling the Delhi-Taylor Oil Corporation Jones #2-24 well located 1980' FWL and 660' FWL of Section 24, T-19-S, R-31-E, Eddy County, New Mexico.

<u>DEGREES</u>	<u>DEPTH</u>	<u>DEGREES</u>	<u>DEPTH</u>
1/2	224	1	6490
1/2	429	1/2	6345
1-1/4	550	3/4	7780
1-1/2	2435	1/2	8250
2	2800	2	8700
2	3100	2-1/2	9046
1	3424	2-3/4	9414
1/4	4240	2-3/4	9807
1/4	4762	3	10170
3/4	5405	3	10730
3/4	6088		

DELHI-TAYLOR OIL CORPORATION

By *B. D. Brazell*
B. D. Brazell
Dist. Prod. Foreman

Sworn to and subscribed before me the undersigned authority on this 24th
day of August, 1964.

Margaret Holley
Notary Public in and for
Midland County, Texas

RECEIVED

AUG 25 1964

O. C. C.
ARTESIA, OFFICE

1. The first step is to identify the problem. This involves understanding the situation and the goals that need to be achieved. It is important to gather all relevant information and to define the problem clearly.

[illegible]

NOTED FOR THE RECORD.

_____ said he did not know anything about the _____ and was not involved in the case.

_____ said he did not know anything about the _____ and was not involved in the case.

~~ALL INFORMATION CONTAINED~~
~~HEREIN IS UNCLASSIFIED~~
DATE 08-10-97 BY [illegible]

RECEIVED

AGRI E S. ALIA

0.0.0
AIRTEL OFFICE