

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN (Other inst
verse side)

IPPLICATE
JOB ON re

Form approved.
Budget Bureau No. 1004-
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL
LC-029390 029357-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Southland Royalty Company

3. ADDRESS OF OPERATOR

21 Desta Drive, Midland, Texas 79705

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

J, 2310 FSL & 1980' FEL, Sec. 30, T-18S, R-31-E

RECEIVED

MAR 14 '88

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Unknown

O. C. D.

ARTESIA OFFICE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Shugart "C"

9. WELL NO.

6

10. FIELD AND POOL OR WILDCAT

Shugart (Y, SR, Q, G)

11. SEC., T., R., M., OR BLK. AND SURVEY OR ADMA

Sec. 30, T-18-S, R-31-E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) Secure WH Press & eval casing XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRUPU. Open tbg valve & release press. LD tbg jt. ND WH. NU BOP.
2. RIH w/4 3/4" bit & bit sub to PBTD 3819'.
3. POH w/bit. RU wireline truck. BIH & correlate to Welex GR-N log run 12-26-64. Run GR-Casing Inspection log from + 3450' to surf. Identify holes & extent of damage.
4. RIH w/pkr & retrievable bridge plug. Confirm indicated holes with press & swb tests. Attempt to circ to surf.
5. POH w/tbg. SI well. If needed: Leave RBP or CIBP between waterflow source & upper weak csg. RDPU.
6. Evaluate well for repair/recompletion or plug and abandon.

RECEIVED
FEB 23 11 31 AM '88

18. I hereby certify that the foregoing is true and correct

SIGNED

Cathy Roberts

TITLE Operations Tech III

DATE 2/22/88

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

3-11-88

*See Instructions on Reverse Side