

APPROVED

SEP 10 1964

ROYNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 10 062376
Unit K

RECEIVED

SEP 11 1964

SUNDRY NOTICES AND REPORTS ON WELLS

ARTESIA OFFICE

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>plugging</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 3, 19 64

Well No. 1 is located 130 ft. from S line and 138 ft. from W line of sec. 22

NE/4 SW/4 Sec. 21
(1/4 Sec. and Sec. No.)

155 30E
(Twp.) (Range)

N.M.P.M.
(Meridian)

Red Hills
(Field)

Eddy
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged well July 15-16-17, 1964. Placed 15 sack cement plug on bottom of hole. Shut off complete. Bailed hole dry. Grouted with 25 C.Y. of ready mix concrete - Top of concrete 320' from surface in 8" casing. Set 4" marker at surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operation can be commenced.

Company Kersey & Company

Address P. O. Box 315

Artesia, New Mexico

38210

By Harold Kersey
Title Owner