

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 06370-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

English Federal ☒

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Hackberry, No.-Yates

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 17-19S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.Mex.

1.

OIL ☒ GAS ☐  
WELL WELL OTHER

2. NAME OF OPERATOR

Hanson Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Box 1515 - Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

2310' FNL & 2310' FWL

Sec. 17, T-19-S, R-31-E, NMPM

Eddy County, New Mexico

RECEIVED

JUN 8 1971

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3512' DF

O.C.C.

ARTESIA, OFFICE

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

T.D. @ 2369'. P.B.T.D. @ 2366'. Perfs. @ 2176-2248'. 8-5/8" @ 569'  
w/50 sx. 5-1/2" @ 2369' w/100 sx.

The captioned well was plugged and abandoned in the following manner  
on October 17, 1970:

1. Displaced hole with heavy mud.
2. Spotted a 25 sx. cement plug @ 2176' across perfs.
3. Cut and recovered 970' of 5½" casing.
4. Spotted 25 sx. cement plug in-and-out of 5½" casing stub.
5. Spotted 25 sx. cement plug in-and-out of 8-5/8" casing shoe @ 569'.
6. Spotted 17 sx. cement plug to surface and erected regulation marker.
7. Cleaned up location for final USGS inspection.

RECEIVED  
JUN 7 1971  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Ronald E. Harrington*

TITLE

Geologist

DATE

6-4-71

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

RECEIVED  
JUL 1 1964  
U.S. AIR FORCE  
AFHQS WASH DC