

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. 114-02573
2. NAME OF OPERATOR Gulf Oil Corporation	6. IF INDIAN, ALLOTTEE, OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 672, Hobbs, New Mexico 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	8. FARM OR LEASE NAME General Edna Corp.
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3562' GL	10. FIELD AND POOL, OR WILDCAT Rush
	11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec 14, T-2-S, R-3-E
	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

660' FSL & 1980' FWL, Section 11, 19-S, 31-E

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT	☐	FRACTURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other) Plugged and abandoned	☐
(Other)	☐		☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11,333' TD.

Pulled tubing and packer. Ran CI BP and set at 11,125'. Loaded 30 lb. heavy. Capped BP with 5 sacks of cement from 11,125' to 11,035'. Rat and recovered 5-1/2" casing from 8200'. Spotted 17 sack cement plug from 8240' to 8140', across 5-1/2" casing at 8200'. Spotted 22 sack cement plug from 6922' to 6822', across Bone Springs formation. Spotted 22 sack cement plug from 5251' to 5151', across Delaware formation. Spotted 22 sack cement plug from 4002' to 3902', across 8-5/8" shoe at 3950'. Cut casing from 2140'. Ran tubing to 1400', unable to go deeper. Loaded hole with 93 sack cement plug from 775' to 670', across 13-3/8" shoe at 700'. Spotted 93 sack cement plug from 66' to surface. Installed dry hole marker. Plugged and abandoned. October 17, 1971. Will advise when location is ready for final inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED C. F. KATLEYERTITLE Area Petroleum Engineer

(This space for Federal or State office use)

APPROVED BY H. L. BEEKMAN
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE SEP 20 1971

DATE _____

*See Instructions on Reverse Side