

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 039879

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 460, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface660' FSL and 1980' FSL, Sec. 11, T-19S, R-31E,
Eddy County, New Mexico.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3577' D. F.

10. FIELD AND POOL, OR WILDCAT

Husk Strawn

11. SEC. T. R. M., OR BLK. AND

SURVEY OR AREA

660' FSL, T-19S, R-31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Spudded well 5-6-67. Drilled 15" hole to 698'. Ran 8" joints
10 3/4" OD (700') casing, set @ 698'. Casing was cemented w/ 500 sacks
class "C" w/ 2% gel and 100 sacks class "C" w/ 2% calcium chloride. Plug
down @ 8:45 P.M., 5-7-67. Cement circulated. Tested casing w/ 1000 PSI
for 30 minutes. Tested OK. WOC 24 hours.

18. I hereby certify that the foregoing is true and correct

SIGNED

Glenn R. Hurd

TITLE Supervising Engineer

DATE

6-26-67

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

USGS-5

FILE JUN 29 1967
R. L. DECKMAN
ACTING DISTRICT ENGINEER

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED
JUN 29 1967
GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO