

CONTINENTAL OIL COMPANY

TRACTOR	V. PERT	LEASE	KING SWD.	LANDING FLANGE ELEV. + FT.	DEPTH FT.	SIZE	WT.	GRADE	DATE:
W.RIG	Dbl.	WELL NO.	4	DEPTHS MEASURED FROM DF	<input type="checkbox"/> RT	<input type="checkbox"/> RB	<input type="checkbox"/> Casing		
CO.	Eddie	STATE N.O.	SION	HEIGHT OF MEASURING POINT FROM LANDING FLANGE					
C.O. SUPERVISOR									

3/9/81 MIRU. Prep to Pull tbg. SION Cost to Date: \$ 900⁰⁰

9
3/9/81 POOH w/ 3" X LINE Tbg, sq its 1795' 13' 3 1/2" sub, & O.D. 10 1/2" ass. h. RTH w/ 3 1/8" RTI H w/ D.C.'s Picket, cut off shoe, 6" Washdown Pipe, 3" D.C.'s a Tag. RTI H 1933 June 9' Progress. SION Cost: \$ 280⁰⁰

3/10/81 Started milling POOH. PK started spinning. POOH w/ 11/8" - D.C.'s + Shoe. RTI H w/ 3 1/8" quic k & arrested 3 1/2" ID + Bumpers sub. Could not clean up. RTI H w/ 3 1/8" RTI H w/ Bumper sub. Caught fish, but could not get loose. Balance Fish & pooh w/ Bumpers sub & overshot. Gapped skin on fish. RTI H w/ can. Shoe & milled up (scraper). SION Cost 1 9556 96

3/11/81 Started milling on Pk w/ 11/8" bottom shoe, very little torque. RTI H still spinning. Could not move - 3 hrs up or down. POOH had 4" pipe at this point. Engaged RTI H. RTI H shoe not caught on wire. RTI H worked picked up wire. Since I started milling Pk skin came off. No progress. SION Cost 1 12,656

3/12/81 Milled 2 hrs w/ engaged bottom shoe. No progress. POOH w/ 11/8" wash over pipe arrested w/ cutters and bottom. Should pull out and file. feed action has 4" thread lost torque. POOH - cut off word off as unhooked pipe. RTI H 1 3 1/8" 05. Bottom sub, pipe + 3 D.C.'s. Capt. Sion could not move Pk up as down. Towed his 1 1/2" OS Pulled out of Sion could not catch fish again. POOH. Big up the tool. RTI H and Durap Brilles T