repressured to 2000# with loss of approximately 100# during first fourteen minutes then leveling out for remaining one minute of test. NO VISIBLE LEAK. PRESSURE LEVELING OUT TOWARDS APPROXIMATELY 1900#.

ODESSA, TEXAS

No delay was observed to operation of blowout control equipment at the conclusion of testing. Closures were made using closing unit pump only to the observed pressure of 1250# for test to ram type bops and 1250# for test to Hydril. Accumulators were pressured to 2200# at end of test. Control valves operated as indicated on closing unit manifold at end of test. Bop extentions were not hooked up. No test desired to top of casing using packer, nor to the upper kelly cock (not in rig inventory at time of test), to the lower kelly cock, or to the drill pipe safety valve.

VELLOW JACKET TOOLS AND SERVICES, INC. Test made by Hubert Nelms Dubut Telme

NO. DE COPIES RECEIVED USTRIBUTION SANTA FE FILE U.S.C.S. LAND OFFICE OFERATOR	3	RECEI NEW MEXICO OIL CONSERVATION C JUN 11 D. C. ARTESIA, C	омміззіон 1974 С.	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State X Fee 5. State Off & Gas Lease No. K-4093
LEG NOT USE THIS FOR USE THIS F	APPLICATIO	NOTICES AND REPORTS ON WELLS BALS TO IFILL ON TO DEEPEN OR PLUS BALS TO A DIFFEN FOR PERMIT - " (FORM C-101) FOP JUCH PROPOSALS.)	IENT PESERVOIR.	7. Unit Agreement Name
2. Name of Operator Eondo Drillin	8. Form or Lease Name Union TX State Com. 9. Well No.			
3. Address of Operator P.O. Box 2516	No. 1 10. Field and Pool, of Wildoat			
4. Lor aloa of Well UNIT LETTERN	. 66	OI FEET FROM THE South LINE AND	1980 FEET FROM	
West	NE, SECTION	TOWNSHIPRANGE	29E	
<u>IIIIIIIIIII</u>	12. County Eddy			
		ppropriate Box To Indicate Nature of No ENTION TO:		her Data T REPORT OF:
PERFORM VEMEDIAL WORK				ALTERING CASING

17. Design the errors and in Completed Operations (Clearly state of pertinent details, and give pertinent dates, including estimated date of starting any proposed worky for ROLE 1103.

On June 7, 1974 at 10:00 P.M. this well had been drilled to a depth of 2776 feet using brine water based fluid in a 12-1/4" hole reduced to 11" at approximately 800 feet. A total of 2776' of 8-5/8" OD H-40 Casing was run and landed @ 2761' ground level. 430' of 8-5/8" 32# and 2346' 24# casing was used.

On June 9, 1974, Halliburton cemented this well with 850 sax of light cement with 1/4th. Lb. of flow seal and 5 Lbs of salt per sax, and 200 sax of Class C neat cement with 2% Cal. Chloride for a total of 1050 sax. Plug down 0 6:15 A.M. An excess of 100 sacks was circulated to the surface.

After waiting 24 hours on cement, Blowout Preventor equipment was installed, a 7-7/8" bit run in hole to approximistely 2000', and pressure tested to 1000 Lbs. FSI for 30 minutes without pressure drop. All O.K.

AU S:00 A.M. on June 10, 1974 this well was drilling @ 3140' in lime.

18. I to reby certify that the intermution above is true and complet	te to the best of my knowledge and belief.	
Meren	TTLE Vice President	DATE 6/10/74
100 may hi ar Susset	OIL AND GAS INSPECTOR	JUN 1 2 1974
CONDITIONS OF APPROVAL, IF ANY:		