

Bennett Wire Line Service
305 McArthur Ave. Ph. (505) 746 - 3281
Artesia, New Mexico - 88210

OCT 15 1974

O. C. C.
ARTESIA, OFFICE

BOTTOM HOLE PRESSURE SURVEY REPORT

OPERATOR HONDO DRILLING COMPANY
LEASE Union "TX" St. Com.
WELL NO. 1
FIELD _____
DATE _____ TIME 8/30/74 to 9/2/74
STATUS _____ 68 Hr. Press. build-up
TEST DEPTH 11,080 Ft.
TIME S.I. _____ LAST TEST DATE _____
CAS. PRES. _____ BHP LAST TEST _____
TUB. PRES. _____ BHP CHANGE _____
ELEV. _____ FLUID TOP None
DATUM _____ WATER TOP "
TEMP _____ RUN BY Bennett
CLOCK NO. _____ GAUGE NO. 8567
ELEMENT NO. 8567

DEPTH PRESSURE GRADIENT

Note: The first pressure before well was shut -in is the flowing pressure on bottom @ depth of 11,080 Ft.
The following pressures on 15 min. intervals to 1 hour, then hourly pressures

H
O
U
R
S

T

I

M

E

250 750 1250 1750 2250 2750 3250 3750 4250 4750

