	- + + + + U	. C. C. COAY -	Copy to SF
DEPARTMEN	ITED STATES NT OF THE INTERI LOGICAL SURVEY	SUBMIT IN TRIPLICATE (Other Instructions on re Verse side)	5. LEASE DESIGNATION AND SERIAL NO. NM 12211
SUNDRY NOTICE (Do not use this form for proposals t Use "APPLICATION	S AND REPORTS C to drill or to deepen or plug ba N FOR PERMIT " for such pr		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
I. OIL GAS WELL OTHER			7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME		
Honeysuckle Explore	Federal 20 9. WELL NO.		
450 Petr. Club. Bld; 4. rocarios of well (Report location clear) See also space 17 below.) At surface 1980 FWL and	2201 1961	rado_80202 State requirements.* ECEIVED	1 10. FIELD AND POOL, OR WILDCAT Shugart 11. SEC., T., R., M., OR BLK. AND SUBVEY OR AREA
	(0)	JAN 1 7 1977	Sec. 20 T18S R31E 12. COUNTY OF PARISH 13. STATE
14. PERMIT NO. 13	5. ELEVATIONS (Show whether DF,	RT, GR, etc.)	N1 N4
16. Chack Appro	3633 Df	O.C.C.	
NOTICE OF INTENTION			QUENT REPORT OF :
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE FROPOSED OR COMPLETED OPERATE proposed work. If well is directionally nent to this work.)* Lost hole as po Well was P&A or 75 sacks at 61 10 sacks at su The Operator w	er Notice 9-331 n 1-31-76. The 0'- base 8-5/8 rface	Completion or Recom details, and give pertinent date ons and measured and true verting dated 2-10-76. following plugs	cal depths for all markers and zones perti-
very near futu			RECEIVED
			JAN 04 1977
			U.S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO
18. I hereby cert/s that the foregoing is tru SIGNED Jearry D. Frank	e and correct	gent	DATE <u>1-3-77</u>
(This space for Federal or State office us APPROVED BY CONDITIONS OF APPROVAL, IF ANY :	Tall TITLE ACT	ing district enginee	R date JAN 1 3 1977
V	*See Instructions	on Reverse Side	

Ĩ

Ĺ

A de la companya de la compan

businesses was

: L

.			c. C. C.		Form approve	a.
Form 9-351 UN. STATES SUBMIT IN TRIPL 7º (May 1963) Other justructions				Budget Burea	Budget Bureau No. 42-R142	
DEPARTMENT OF THE INTERIOR Verse side)			5. LEASE DESIGNATION AND BERIAL NO NM-12211			
		GEOLOGICAL SURVE		5m-	6. IF INDIAN, ALLOTTER	OR TRIBE NAM
SU (Do not use th	NDRY NOT dis form for propo	ICES AND REPOR	plug back to such proposal	a different restrict		
1. OIL CAS OTHER			JAN 04 1977	7. UNIT AGREEMENT NAME		
WELL LA WELL OTHER U.S. GEOLOGICAL SURVEY 2. NAMB OF OPERATOR U.S. GEOLOGICAL SURVEY Honeysuckle Exploration Corporation ARTESIA, NEW MEXICO			8. FARM OR LEASE NAME			
Honeysuckle Exploration Corporation ARTESIA, NEW MEXICO			Federal 20			
3. ADURESS OF OPERATOR 450 Petroleum Club Building, Denver, Colorado 80202			J. WELL NO.			
450 Petrolet	(Report location of	Laing, Denver, Co	th any State	regulrements.*	10. FIELD AND POOL, 0	R WILDCAT
See also space 17 1 At surface	elow.)			•••	Shugart	
1980' FWL and 330' FSL			11. SDC., T., R., M., OR BLK. AND SUBVEY OR AREA			
1900 1901 (2	a 990 - 02				Sec.20, T188.	
		15. ELEVATIONS (Show whe	. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH	13. STATE
		3633' DF	3633' DF		Eddy	N.M.
16.	Check A	ppropriate Box To Indic	ate Nature	of Notice, Report, or	Other Data	
NOTICE OF INTENTION TO : SUBSE				QUENT REPORT OF:		
TEST WATER SHU	-0FF	PULL OR ALTER CASING]	WATER SHUT-OFF	REPAIRING	WDLI.
FRACTURE TREAT		MULTIPLE COMPLETE	-	FRACTURE TREATMENT	ALTERING C.	ASING
SHOOT OR ACIDIZ		ABANDON*	-	SHOOTING OF ACIDIZING	ABANDONME	NT*
REPAIR WELL		CHANGE PLANS	-	(Other)	ts of multiple completion	
(Other)				Completion or Recom	pletion Report and Log for	rm.)
nent to this worl	.) •	ERATIONS (Clearly state all possible of the subsurface of the subs		•		
airculation 7	one 680'-70	0'. Set drill pi	ipe at 7	68'. Spotted 20	0 sxs. Thixset	Class "C
circulation 2						nnig Wr
with 6#/sx Gi	lsonite, 1/	4# /sx Flocele # Fluid level appe	and 3% C	alcium Unioride.	Displaced w/)	

Attempted to set drill pipe back at 768' but could not get past 700' because of cement. Attempted to load hole without success. Spotted 200 sxs. Thixset Class "C" Plug W/6# / sx. Gilsonite, 1/4# /sx Flocele and 3% Calcium Chloride. Dispaced with 3 bbls. water. Pulled drill pipe from hole. Fluid appeared to be at 150'. No cement on pipe. Waited 4 hrs. and then attempted to load hole without success.

Notified Artesia office of U.S.G.S. of intention to plug and the work done below was done with their approval.

Set drill pipe at 700'. Spotted 200 sxs. Thixset Class "C" Plug with 6#/sx. Gilsonite. 1/4#/sx. Flocele and 3% Calcium Chloride. Displaced with 3 bbls. water. Pulled drill pipe from hole. Fluid level appeared to be @ 300'. Cement on two joints. Waited 4 hrs. and then attempted to load hole without success. Pushed 8-5/8" Top Wooden Plug down to bottom of surface casing at 610' with drill pipe. Loaded hole successfully with brine water. Waited 10 minutes with no sign of fluid level dropping. Mixed 75 sxs. of Class "C" neat cement. Pulled drill pipe out of hole. Loaded hole to check if fluid level was dropping and it was not. Plug holding.

18. I hereby rertify that the foregoing is true and correct DATE ____2-10-76 TITLE Authorized Agent SIGNED in the management of the second 2 = 12 - 21 (This space for Federal or State office use ACTING DISTRICT ENGINEER DATE JAN 1 3 1977 Vae Tara APPROVED BY TITLE . CONDITIONS OF APPROVAL, IF ANY :

*See Instructions on Reverse Side