Submit 3 Copies to Appropriate District Office	State of Ene _,, Minerals and Na			partment		Form C- Revised		
DISTRICT J P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION 2040 Pacheco St.					WELL API NO.	P		
DISTRICT II Santa Fe, NM 87505 P.O. Drawer DD, Artesia, NM 88210					Indicate Type of Lease			
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410					•State Oil & Gas Lease No. 648			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					PLease Name or Unit Agreement Name East Millman Unit			
1 Type of Well: OIL GAS WELL WELL OTHER P&A								
2Name of Operator SDX Resources, Inc.					®Well No. 219			
sAddress of Operator PO Box 5061, Midland, TX 79704					^{sP} ool name or Wildcat E Millman QN-GB-SA			
4Well Location Unit LetterJ1650	Feet From The East	t	Line and	1980	Feet From The	South	Line	
Section 15	Township 195	S R	lange	28E	NMPM	Eddy c	ounty	
	₀Elevation (Show whe 3449' GR	ether DF, F	RKB, RT, GR, et	с.				
¹¹ Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data								
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:								
			REMEDIAL WORK ALTERING CASING					
	CHANGE PLANS			DRILLING OF	PNS.	PLUG AND ANBAND		
PULL OR ALTER CASING		CASING TEST AND CEME						
OTHER: OTHER:								
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.								
Well was originally P&A'd as DHY State A #1.								
On September 1, 1993 the name was changed to East Millman Unit #219.								
On September 1, 1993 the name was changed to East Millman Unit #219. On August 13, 1993 the following work was done: Dug workover pit. Dug out around 8-5/8" csg. Cut off & removed dry hole marker. Welded on 8-5/8" csg stub to surface. The well was never re-entered beyond the above mentioned work. On November 30, 2000 the dry hole marker was re-installed.								
The well was never re-entered beyond the above mentioned work.								
On November 30, 2000 the dry hole marker was re-installed.							1010	
SDX proposes to P&A the well as follows:								
 Change well name back to original name (DHY State A #1). Fill pit. Clean location 								
	al name (DHY State A #1).							
3. Clean location. I hereby certify that the information above is tr		y knowled	ge and belief.					
3. Clean location.			ge and belief. _{LE} Engineer			DATE 11-30-0		
3. Clean location.							0	
3. Clean location. I hereby certify that the information above is tr SIGNATURE						DATE 11-30-0	0	