

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYCOPY
SUBMIT IN TRIPLICATE*
(Other Instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM - 1358

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug. Use "APPLICATION FOR PERMIT—" for such proposals.)

OCT 5 1976

O.C.G.
ARTESIA, OFFICE

7. UNIT AGREEMENT NAME

CC Tank Unit

8. FARM OR LEASE NAME

CC Tank Unit Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 12-20S-23E

Unit J NMPM

12. COUNTY OR PARISH

Eddy

13. STATE

NM

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th Street - Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

1650' FSL & 1980' FEL of Sec. 12-20S-23E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3990' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

PB, and run 4½" Prod Csg X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 9080'; PETD 6773' - 9-10-76 - Set two plugs as follows: 50sx of Class "C" at 8525-8375' KB, 50 sx Class "C" w/2% CaCl 7000-6850'. Laid down DP and ran 217 joints of 4½" 10.5# K-55 ST&C (6829') w/9 centralizers, guide shoe set at 6810' KB. Float Collar w/Auto fill at 6773' KB, cemented w/250 gallons mud flush, 175 sacks of Class "C" w/0.5% CFR-2 and 3# salt, 275 sacks of Halli-Lite and 100 sacks of Class "C" w/0.5% CFR-2 and 3# salt, displaced w/20 bbls 2% KCL and 88 bbls fresh water, bumped plug w/1500 psi. OK. PD 10:30 AM 9-10-76. Set slips and released rig at 2:00 PM 9-10-76.

RECEIVED

SEP 30 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Christine Tomlinson

TITLE

Geol. Secty

DATE 9-30-76

(This space for Federal or State office use)

APPROVED BY

Joe D. Lara

TITLE

ACTING CHIEF ENGINEER

DATE OCT 4 1976

CONDITIONS OF APPROVAL, IF ANY: