

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-12211

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 20

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Shugart

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 20-18S-31E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Honeysuckle Exploration Corp.

3. ADDRESS OF OPERATOR

450 Petroleum Club Bldg., Denver, CO 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

1650' FSL, 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3633' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Drilled to 4025' - Ran Electric logs with no commercial shows. Obtained verbal authority from R. L. Beekman, USGS, Artesia, N.M. to plug and abandon on 7-24-76. Spotted 35 sx (100' +) plugs at 3500' - 3600', 3150' - 3250', 1850' - 1950'. Set cement retainer @ 630' and pumped 50 sx below, spotted 10 sx above. Retainer failed to hold and allowed flow back from water zone at 1800'.

On 7-27-76 pumped 300 sx cement through 8 5/8' casing. Calculated 100 sx below casing @ 654' and casing left full from 654' to surface. Shut well in for 36 hours, checked and plug holding OK. Will set marker at surface.

Well P&A on 7-27-76

RECEIVED

AUG 11 1976

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

President

DATE

8-2-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: