

COMPANY <i>Mesa Oil Co</i>	PROPERTY NAME <i>A. Dooley</i>	WELL NO. <i>1</i>
-------------------------------	-----------------------------------	----------------------

DATE	LOCATION ULSTR) <i>D 4-19-28</i>	FOOTAGE
------	-------------------------------------	---------

API NO.	POOL
---------	------

- ① RIH w/ collar locator + find perforations
- ② Spot 40-5x c perts + tag
- ③ Spot 30 5x or 100' plug c GB 2054'
- ④ Spot 30 5x or 100' plug c Qu 1690'
- ⑤ Perforate c 716' + sg. 30 5x outside of pipe leaving 100' inside
- ⑥ Perforate c 285' + attempt to circulate cement to surface on backside leaving pipe full.
- ⑦ Clean + level location + set P+ A marker
- ⑧ Place mud between pluggs
- ⑨ Contractor is responsible for location + roads.

Before

10" e
235'

8 1/4" e
676

CASING RECORD:

10" e 235'

8 1/4" e 676

There is no record of production csg.

There is no record of cementing.

Records show a plug c 2871'

Formation tops

San Andres e 2490'

GB e 2054'

Qu e 1690'

BX e 610'

TX e 368'

2871'

