Form 9-331
(May 1963)

UNITED STATES
DEPARTME ˙ OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructio˙ ˙n re-
verse side)

Form approved.'
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-01403

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1.

OIL WELL ☐   GAS WELL ☒   OTHER

RECEIVED

2. NAME OF OPERATOR

Gulf Oil Corporation

3. ADDRESS OF OPERATOR

Box 670, Hobbs, New Mexico 88240

MAR 7 1977

O. C. C.
ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FS & EL, Section 20, 18-S, 31-E

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Littlefield EM Fed Com

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 20, 18-S, 31-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3629' GL

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) _____	
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

11,145' TD.
Reached total depth of 8-3/4" hole at 11,145' at 10:15 AM, February 24, 1977. Ran 294 joints and 1 cut joint, 12,124' of 7" OD 26# and 23# N-80 and K-55 LT&C casing set and cemented at 12,145' with 900 sacks of Class H with .75% CFR-2 and 5# KCC per sack. WOC 8 hours. Temperature survey indicated TOC at 7960'. WOC over 18 hours. Tested casing with 3,000#, 30 minutes, OK.

RECEIVED
MAR 03 1977
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED _D. F. Berlin_   TITLE Area Engineer   DATE March 2, 1977

(This space for Federal or State office use)

APPROVED BY _____   TITLE ACTING DISTRICT ENGINEER   DATE MAR 4 1977
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side