

UNITED STATES DEPARTMENT OF THE INTERIOR

(Other Instructions on reverse side)

Budget Bureau NO. 42-11324

GE OLOGICAL SURVEY

5. LEASE DESIGNATION AND SERIAL NO.

NMO 556285

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Copy to 51

1.

OIL WELL ☐ GAS WELL ☒ OTHER

APR 26 1977

2. NAME OF OPERATOR

Southern Union Supply Company

3. ADDRESS OF OPERATOR

Suite 1800, First International Bldg, Dallas, Texas 75270

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

660' FEL and 1980' FSL of Section 26, T-20-S, R-25-E

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Exxon Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 26, T-20-S, R-25-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3721 G.L.

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Setting Casing

XX

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Drilled 12 1/4" hole to 2500'

2. Ran 8-5/8", K-55, 24# casing.

4/11/77

3. Cemented with 1000 sacks of Halco Light with 5# gilsonite, 2% CaCl, 1/4# Flocele, and 200 sacks Class "C" with 2% CaCl. Circ 130 sacks cement.

RECEIVED

APR 22 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

B. B. ...

TITLE

Consulting Engineer for
Southern Union Supply Co.

DATE

4/15/77

(This space for Federal or State office use)

APPROVED BY

Joe L. ...

TITLE

ACTING DISTRICT ENGINEER

DATE

APR 25 1977

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side