

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
Southern Union Exploration Company of Texas
3. ADDRESS OF OPERATOR
1217 Main Street, Dallas, Texas 75202
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1880 W 880
AT SURFACE: 660' FSL and 1980' FSL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Change of operator's name and address

SUBSEQUENT REPORT OF:

RECEIVED
FEB 12 1981
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Change of operator's name and address, effective 12/30/80

Southern Union Exploration Co.
1217 Main Street
Dallas, Texas 75202

RECEIVED
FEB 19 1981

U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Drilling & Production Eng. DATE February 1981

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

5. LEASE
NM 0556285
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Exxon Federal
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
West Bubbling Springs Morrow
11. SEC., T., R., M OR BLK. AND SURVEY OR AREA
Sec. 25, T20S, R25E
12. COUNTY OR PARISH
Eddy
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DE KDB AND WD)
3695' GL

NOTE: Report results of multiple completions or zone change on Form 9-330.

U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO