

Chama Petroleum Company

Exploration and Production
P.O. Box 31405
5447 Glen Lakes Drive
Dallas Texas 75231
214-739-1778

August 9, 1985

REGISTERED MAIL

Mr. Weaver
New Mexico Oil Conservation Division
Drawer DD
Artesia, New Mexico 88210

Re: Morrison Com #1

Dear: Mr. Weaver:


This letter is to advise you that the pilot for the well as referenced above cannot be seen without a close inspection of the flare unit. Our pumper is Roger Kingerey who works for Gray Pumping Service and we have no reason to believe that he handled the well anything but correctly. He has advised that our pilot does and is working correctly.

Please be aware that this well does not always produce gas, therefore, it does not always produce a visible gas flare, however, since there are continuing complaints from a resident in the area of a gas smell, we have gone to the expense of digging a pit and have laid a flow line, in addition to the work already done on the auto pilot, so that this situation will not occur in the future.

If this resident continues to report gas odor, we would like to request either her home or the other various pipelines in the area be checked for gas leaks.

Sincerely,

CHAMA PETROLEUM COMPANY



Mark K. Nearburg
Landman

MKN/srs