

DEVIATION TESTS

for

TEXAS OIL & GAS CORPORATION
9th Floor - Wilco Bldg
Midland, Texas 79701

EXXON STATE COM "B" #1
1650' FNL & 1980' FEL
Sec 29, T19S, R28E
Eddy County, New Mexico

DEPTH (FEET)	DEVIATION (DEGREES)	CUMULATIVE DISPLACEMENT	DEPTH (FEET)	DEVIATION (DEGREES)	CUMULATIVE DISPLACEMENT
240	1/2	2.1	5,063	3-3/4	111.8
500	1-1/4	7.8	5,156	3-1/2	117.5
725	3/4	10.7	5,219	3-1/2	121.3
1,000	3/4	14.3	5,313	3	126.2
1,063	3/4	15.1	5,408	2-1/4	129.9
1,438	3/4	20.0	5,502	2	133.2
1,752	1/2	22.7	5,770	1-3/4	141.4
2,160	1/2	26.3	6,022	2	150.2
2,568	3/4	31.6	6,189	2	156.0
2,815	1-1/4	37.0	6,405	1-1/2	161.7
3,000	1	40.2	6,815	3/4	167.1
3,307	1-1/4	46.9	7,316	1/4	169.3
3,620	1-1/4	53.7	7,820	1/2	173.7
3,922	1-1/2	61.6	8,198	2	186.9
4,288	1-1/2	71.2	8,407	2	194.2
4,561	2-1/2	83.1	8,814	1-3/4	206.6
4,750	3	93.0	9,442	1-1/2	223.0
4,844	3-1/4	98.3	10,567	1/2	232.8
4,937	3-1/4	103.6	11,029	3/4	238.8

B. E. Burton

B. E. Burton
Warton Drilling Company