

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

FEB 20 1978

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Geo <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Nix "IT" Com
9. Well No. 1 1
10. Field and Pool, or Wildcat Und. Cemetery Mrwr
12. County Eddy

SUNDRY NOTICES AND REPORTS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

O.C.C. ARTESIA OFFICE

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
Yates Petroleum Corporation ✓

3. Address of Operator
207 South 4th Street - Artesia, NM 88210

4. Location of Well
UNIT LETTER P 660 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 13 TOWNSHIP 20S RANGE 24E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3580' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 17½" hole at 8:00 AM 1-30-77.

TD 300' - Ran 7 joints of 13-3/8" 48# H-40 casing *305') set at 300'. 1-Float Shoe at 263'. Cemented w/315 sacks of Class "C" 4% CaCl. Slurry wt. 14.8, 1.32 cuft/sx. Compressive Strength at 70 deg 1023 psi in 12 hours. PD 4:30 AM 1-31-78, Cement did not circulate. WOC and filled hole w/11 yards of Ready-mix. WOC 12 hours, cut off and reduced hole to 12¼", drilled plug and tested to 600#. OK. Resumed drilling.

TD 1405' - Ran 31 joints of 8-5/8" 24# J-55 (1405') of casing set at 1405'. Flapper insert at 1366'. 2 centralizers and 1 basket. Cemented as follows: 250 sacks of RFC-2 + 2% CaCl, 600 sacks of 50-50 poz + 4% D-20 + 5#/sack D-24 + 1/4#/sx D-29 2% CaCl. Tailed in w/150 sacks of Class C 2% CaCl. Circulated 100 sacks to surface. PD 9:00 PM 2-2-78. WOC 18 hours NU and tested BOP's to 1500#. OK. Reduced hole to 7-7/8", drilled plug and tested to 600#. OK and resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine Ambrose TITLE Geol. Secty DATE 2-17-78

APPROVED BY R. A. Gussert TITLE SUPERVISOR, DISTRICT II DATE FEB 21 1978

CONDITIONS OF APPROVAL, IF ANY: