Form 9–331 Dec. 1973	Form Approved.
UN. 2D STATES	Budget Bureau No. 42R1424
DEPARTMENT OF THE INTERIOR	5. LLASE
	NM 14118
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NOTEEIVED
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	JAN 31 1980
	8. FARM OR LEASE NAME
1. oil gas vell other Dry Holo	Yates Fed A Gas Com O. C. D.
2. NAME OF OPERATOR	9. WELL NO ARTES!A, OFFICE
Amoco Production Company	
3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME
P.O. Drawer A, Levelland, Texas 79336	Und. Morrow
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	
AT SURFACE: 660'FNL & 660'FEL, Sec 21, (Unit	21-19-24 12. COUNTY OR PARISH 13. STATE
AI TOP PROD. INTERVAL: A NEL NEL)	Eddy NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR ADDROVAL TO SUCCESS	3700.2GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	
SHOOT OR ACIDIZE	of of the standard s
REPAIR WELL	
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
CHANGE ZONES	
ABANDON*	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent	all pertinent details, and give pertinent dates, rectionally drilled, give subsurface locations and t to this work.)*
Evaluated well and determined that well was not	commercially productive Pluggod
as follows: Moved in casing pullers 8/27/78. Cu	t_{5} casing at 5071 and null casing
Spor zo sxs class H cement 8/65'-8615'.	
Spot 80 sxs Class H cement 5123'-4910' in a	nd out of casing stub
Spot 50 sxs class H cement 3350'-3250'.	
Spot 50 sxs Class H cement 1650'-1560'.	
Spot 10 sxs Class H cement 1560'-surface.	
	the state of the s
Released rig 4-10-78. Erected abandonment marke	r. 1017 (1 52) (14)
· .	
Subsurface Safety Valve: Manu. and Type	Set @Ft.
18. I hereby certify that the foregoing is true and correct	문화 관심의 ⁻ 나는 - 다양한 한
SIGNED Kay W. Cork TITLE Adm. Supv.	DATE8/30/78
(This space for Federal or State office	
アンチーマンズ キードアウロショウ なー 教育大学家	
APPROVED BY CONSISTENT OF A PPROVAL, IF ANY: OH4-USGS-Art 1-Yates Petro Corp 1-Div	JL EIBRENEEN A WAIT TO US DOOD
U+4-USGS-Art 1-Yates Petro Corp	3.
i-bit i-biton lexas Petro. torp.	3000202 표 정권 강권인사
1-Susp	· · · · · · · · · · · · · · · · · · ·
1-RC	opsie ov 2012

,

•

.

•

۲

*See Instructions on Reverse Side