

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☐
LAND OFFICE	☐
OPERATOR	☒

5a. Indicate Type of Lease
State ☐ For ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A D
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED BY

JAN 09 1984

O. C. D.

ARTESIA, OFFICE

1. OIL WELL ☐ GAS WELL ☐ OTHER: Re-entry

2. Name of Operator

Chama Petroleum Company ✓

3. Address of Operator

P.O. Box 31405, Dallas, Texas 75231

4. Location of well

UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM
East 22 TOWNSHIP 19S RANGE 25E N.M.P.M.

7. Unit Agreement Name

8. Term of Lease Name

B&B

9. Well No.

1

10. Field and Pool, or Wildcat
Und. Boyd Morrow

11. Elevation (Show whether DF, RT, GR, etc.)

3456' GL

12. County

Eddy

13. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER Activity ☐

14. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-3-82

Thru

Waiting on Completion

11-15-83

11-16-83: R.U. P.U., ran PDC log from 9378 to 5800', S.I.

11-17-83: Perf. with 4 S.P.F. from 9319' to 9328', T.I.H., S.I.

11-18-83: Broke perms down, reset pkr., pkr. leaking, S.I.

11-19-83: POOH with tubing & pkr., T.I.H. with repaired pkr., acidized with 3000 gal. Morrow BC containing 1000 STC nitrogen per bbl., removed isolation tool, flowed well back to pit, had steady flare, S.I.

11-20-83: S.I.

11-21-83: Swab, recovering very small amount of load water with flare increasing, S.I.

11-22-83: SITP 2500#, 2500# on casing, had equalized overnight, test & found leaking on/off tool, POOH, S.I.