COC COPY

RECEIVLD

Capeji to SI R1424

Form	Approvéd	l. "	
Budge	t Bureau	No.	42-F

UNITED STATES				
DEPARTMENT	OF	THE	INTERIOR	
GEOLOGI	CAL	SHE	VFY	

JAN 2 4 1979-029392-b

DEPARTMENT OF THE INTERIOR OF IT	¥ 1373
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
RECEIVED.	OFFILINIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS AND REPORTS ON	Drenewo of the bradlens
(Do not use this form for proposals to drill or to deepen or pure bate 1919 different reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas well other U.S. GEULUGICAL SURVEY	Greenwood PreGrayburg Unit Factorial Street
2. NAME OF OPERATOR VARIESIA, NEW MEXICO	11 वर्ष्ट्रेन ह है के
Amoco Production Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Shugart-Silurian-Devonian
P.O. Drawer "A", Levelland, Texas 79336 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 2014年 高高音音
below.) AT SURFACE: 1980' FSL &660' FWL, Sec34(Unit L,	34-18-31
AT SURFACE: 1960 196 addo 1 WE, 36634(01116 E, AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE NM
AT TOTAL DEPTH:	14. API NO. 1244 2 6443
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	111 1 2 2 2 3 3 <u>1</u>
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3613.5 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3 1 2 3 1 2
TEST WATER SHUT-OFF	to popular
FRACTURE TREAT US SHOOT OR ACIDIZE US	of control of the con
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE	Site of the control o
CHANGE ZONES	6 급호회을 된 등등경에 다
(other) Ran casing & test	Construction of the control of the c
 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is different and true vertical depths for all markers and zones pertinent. On 12/2/78, drilled to TD 12,220' and ran 5 and 17# N-80 LT & C (9140') casing set at 12 sx Trinity Lite with 3/4% CFR and 2 1/4# floor with 3/4% CFR and 5# salt/sx. PD 9:30 P.M. temperature survey, estimated top of cement at 12/3/78. Test with 1000# for 30 minutes. To subsurface Safety Valve: Manu. and Type Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct 	irectionally drilled, give subsurface locations and to this work.)* 1/2" 20# N-80 LT & C (3080') 1/2" 20# N-80 LT & C (3080'
71 1	visor DATE January 16, 1979
APPROVED BY Jack XI. Land TITLE THE DISTRICT E	NGINEGRIE JAN 29 1979
CONDITIONS OF APPROVAL. IF ANY:	
0+4-੯SGS-A 1-Houston	Harrie CH Charl
1-Nous con	tibnes
1-DE *See Instructions on Reverse	Side ·