

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM OIL CONS. COMMISSION
Drawer DD
Artesia, NM 88210
SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Yates Petroleum Corporation		8. FARM OR LEASE NAME Reddy Trigg JV Federal
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210		9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980/N 660/E, Sec. 35-19S-27E		10. FIELD AND POOL, OR WILDCAT Angell Ranch Atoka Morrow
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit H, Sec. 35-T19S-R27E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3433' KB		12. COUNTY OR PARISH Eddy
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input checked="" type="checkbox"/>
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in workover unit and found tubing parted with split collar at about 5100', and 4-1/2" casing apparently parted at about 3100'. We propose to pull the casing and evaluate the damage. If repairable, will repair and proceed with plugback and recompletion in the Strawn; but if excessive damage is evident, we propose to P&A the well with cement plugs in the 4-1/2" casing, open hole section and in the 8-5/8" Intermediate casing:

25 sx @ 10280 - 9920
25 sx @ 8860 - 8500
45 sx @ 3300 - 3000
35 sx @ 2435 - 2335
15 sx @ Surface w/dry hole marker.

RECEIVED
JAN - 7 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Eddie L. Indych

TITLE Engineer

DATE 1-6-82

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:
JAN 8 1982

FOR
JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side