

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 7043

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Langley-Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 4-20S-23E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

Beard Oil Company

3. ADDRESS OF OPERATOR

2000 Classen Bldg., 200 South, Oklahoma City, Okla. 73106

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

990' FNL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4067.6'

AUG 14 1978

RECEIVED

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Setting surf & intermediate csgrx

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 2:00 P.M. 7-25-78. Drilled 17" hole to 280'. Cemented 13-3/8" 54#, H-40 casing @ 280' with 250 sxs Class "C" cement. Plug down 7-27-78. Drilled 11" hole to 1773'. Cemented 8-5/8" 20#, K-55, ST&C casing @ 1773' with 450 sxs Halliburton Lt. Wt. cement with 5# Gilsonite & 1/4# Flocele per sack, followed with 200 sxs Class "C" with 2% CaCl. Cement did not circulate. Filled up around top to surface with 6 yards Redi-mix cement. Plug down @ 1:00 P.M. 7-31-78.

RECEIVED
AUG 7 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

James W. Vater

TITLE Vice President

DATE 8-3-78

(This space for Federal or State office use)

ACTING DISTRICT ENGINEER

APPROVED BY (Orig. Sgd.) ALBERT R. STALL

TITLE

DATE

AUG 11 1978

CONDITIONS OF APPROVAL, IF ANY: