

EXXON COMPANY, U.S.A.
POST OFFICE BOX 1600 • MIDLAND, TEXAS 79702

MIDCONTINENT PRODUCTION DIVISION

H. G. DAVIDSON
DRILLING MANAGER

May 31, 1979

LISTED BELOW ARE THE DEVIATION TESTS TAKEN ON OUR NEW MEXICO STATE
"CU" NO. 3.

<u>DEPTH</u>	<u>DEGREES OF DEVIATION</u>
100	1/4°
229	1/4°
380	3/4°
770	3/4°
1,055	1/4°
1,304	3/4°
1,492	1-1/4°
1,649	1-3/4°
1,704	1-1/2°
1,830	1-1/2°
1,997	1-1/4°
2,130	1-1/4°
2,320	3/4°
2,860	1-1/4°
3,060	1°
3,280	1°
3,560	1-1/4°
3,870	1-1/4°
4,126	1°
4,410	1°
4,730	1/2°
5,032	1°
5,335	3/4°
5,685	3/4°
6,188	1°
6,597	3/4°
7,095	1°
7,598	1-1/4°
7,725	1-1/2°
8,067	1-3/4°
8,445	1-3/4°
8,945	2°
9,280	3-1/2°
9,382	2-3/4°
9,600	1-3/4°
10,400	1-1/2°