

Form 9-331  
(May 1963)UNIT STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLIC  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 6019

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1.

OIL ☐ GAS ☒  
WELL WELL OTHER

2. NAME OF OPERATOR

MESA Petroleum Co.

JUL 9 1979

3. ADDRESS OF OPERATOR

1000 Vaughn Building, Midland, Texas 79701

O. C. C.  
ARTESIA, OFFICE4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

Unit H, 1980' FNL &amp; 660' FEL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

RUNYAN FEDERAL

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

SEC 18, T19S, R23E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4081.2 GR

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

Spudded &amp; 13 3/8" Casing

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded well at 0700 on 22 June 1979, 17-1/2" hole. Ran 8 joints 13-3/8", 54.40# K-55 ST&C, set at 253' RKB, float at 205'. Cemented with 275 sacks Class "C" plus 2% cc. Plug down at 0530 on 23 June 1979, circulated five sacks to pits. WOC 18 hours. Tested casing to 600 psi, ok. Reduced hole to 12-1/4" and drilled ahead.

RECEIVED

JUN 27 1979

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*R. E. Math*

TITLE

Regulatory Coordinator

DATE

June 26, 1979

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) ALBERT R. STALL  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACTING DISTRICT ENGINEER

DATE

JUL 05 1979

\*See Instructions on Reverse Side

XC: JLF, JWH, MEC, FILE, USGS