

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

NM OIL CONS.  
Braver DD  
Artesia, NM

COMMISSION

NM-6019

88210 INDIAN, ALLOTTEE OR TRIBE NAME

RECEIVED

OCT 16 1981

C. C. D.

ARTEZIA, NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR ☒  
Mesa Petroleum Co.
3. ADDRESS OF OPERATOR  
1000 Vaughn Bldg., Midland, TX 79701-4493
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: Unit H, 1980' FNL & 660' FEL  
AT TOP PROD. INTERVAL: Same  
AT TOTAL DEPTH: Same

7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME  
Runyan Federal
9. WELL NO.  
2
10. FIELD OR WILDCAT NAME  
Runyan Ranch Wildcat Morrow
11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA  
Sec. 18, T19S, R23E
12. COUNTY OR PARISH  
Eddy
13. STATE  
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
4081.2 GR.

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

- |                      |                          |                          |
|----------------------|--------------------------|--------------------------|
| TEST WATER SHUT-OFF  | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT       | <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE     | <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL          | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE    | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES         | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON*             | <input type="checkbox"/> | <input type="checkbox"/> |

(other) ☒ Bring risers up on 13-3/8" & 8-5/8" csg.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On 8/28/81, risers were brought up on the 13-3/8" casing and the 8-5/8" casing, and the cellars were filled with pea gravel. Work was inspected by Michael Williams of the Artesia NMOC.

RECEIVED  
OCT 9 1981

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Cathy Wickerson TITLE Prod. Recds. Analyst DATE 10/6/81

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

XC: USGS, TLS, MEC, LAND, CNT RCDS, ACCTG, D&M, PARTNERS, FILE

\*See Instructions on Reverse Side

ACCEPTED FOR RECORD

OCT 1 1981

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO