

N. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

OCT 31 1979

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-9739

SUNDRY NOTICES AND REPORTS ON WELL

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	N/A
TENNECO OIL COMPANY	8. Farm or Lease Name
3. Address of Operator	STATE HL-11
6800 Park Ten Blvd., Suite 200 N., San Antonio, TX. 78213	9. Well No.
4. Location of Well	2
UNIT LETTER <u>G</u> , 1980 FEET FROM THE <u>North</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>19S</u> RANGE <u>29E</u> NMPM.	10. Field and Pool, or Wildcat
	Undesignated Turkey Tract (Morrow)
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3374' GR.	Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/5/79 - Set 7 JTS. 13 3/8" New 54.5# K55 8RST&C @ 311' W/500 sxs "C" + 2% CACL₂
+ A7 - Did not circulate to surface topped out w/5 cu. yds. of Redimix hole.
Hole filled and stayed full. WOC. 18 hrs. - Tested 600 PSI.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED F. R. Bell TITLE STAFF PRODUCTION ANALYST DATE 10-29-79
APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE NOV 1 1979
CONDITIONS OF APPROVAL, IF ANY: