

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

OCT 31 1979

ARTESIA OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐
1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		5. State Oil & Gas Lease No. L-2919
2. Name of Operator Yates Petroleum Corporation		7. Unit Agreement Name
3. Address of Operator 207 South 4th Street - Artesia, NM 88210		8. Farm or Lease Name SRC KZ State
4. Location of Well UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>1</u> TOWNSHIP <u>19S</u> RANGE <u>24E</u> NMPM.		9. Well No. 1 5
15. Elevation (Show whether DF, RT, GR, etc.) 3663' GR		10. Field and Pool, or Wildcat Und Penasco Draw SA Yeso Assoc.
12. County Eddy		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐	REMEDIAL WORK ☐ COMMENCE DRILLING OPS. ☒ CASING TEST AND CEMENT JOB ☒ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐ Change Name SRC State KZ to ☒ SRC "KZ" State #5

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 15" hole at 12:30 PM 10-9-79.

TD 312' - Ran 8 joints of 10-3/4" 32# K-55 ST&C (312') of casing set at 312'. 1-insert float at 270'. Cemented w/290 sacks of Class C 4% CaCl. PD 11:30 PM 10-9-79. Cement circulated 75 sacks to surface. WOC 12 hours backed off, reduced hole to 9-7/8", drilled plug and tested to 600# OK, resumed drilling.

TD 1007' - Ran 25 joints of 7" 23# ST&C K-55 (1007') of casing set at 1005'. 1-Guide shoe at 1005', insert float at 965'. Cemented w/100 sacks Thick-Set 300 sacks Halliburton Lite, 100 sacks Class C 2% CaCl. PD 12:45 PM 10-10-79. Cement did not circulate. WOC 6 hours. Ran Temperature Survey and found top of cement at 600'. Pumped 50 sacks Class C 4% CaCl at 500'. WOC 4 hours, tagged cement at 400', spotted 160 sacks Class C 4% CaCl. Cement circulated 25 sacks to surface. WOC 18 hours. NU & tested to 1000# OK. Reduced hole, 6 1/4" drilled plug and tested to 600#. OK, resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine Imbrun TITLE Geol. Secty DATE 10-30-79

APPROVED BY W.A. Gressett TITLE SUPERVISOR, DISTRICT II DATE NOV 1 1979

CONDITIONS OF APPROVAL, IF ANY: