

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. CATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 12833

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rio Penasco MF Fed.

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Undes. Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASec. 11-19S-25E
NMPM Unit F

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Yates Petroleum Corporation

JAN - 3 1980

3. ADDRESS OF OPERATOR

207 South 4th Street - Artesia, NM 88210

O. C. D.

OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL & 1980' FWL of Section 11-19S-25E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3453/9' GR

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Spud

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 17½" hole at 2:00 PM 12-5-79.

TD 400'. - Ran 10 joints of 13-3/8" 48# H-40 ST&C (427') of casing set at 400'
Cemented w/350 sacks of Class C 4% CaCl. PD 11:30 PM 12-6-79. Cement did
not circulate. Filled hole w/4 yards of Ready-Mix. Slurry weight
14.8, 1.32 cu ft/sack. Compressive strength at 70 degrees 1023 psi in 12
hours. WOC 12 hours. Backed off and reduced hole to 12¼". Drilled plug
and tested to 600#. OK. Resumed drilling.

RECEIVED

DEC 31 1979

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Christine Romo

TITLE

Geol. Secty

DATE

12-31-79

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

A. STALL

ACTING DISTRICT ENGINEER

TITLE

DATE

DEC 31 1979