

Phone
713-790-9132

LYNES, INC.

Box 12486
Houston, TX 77017

Address
Midland, Texas 79701

Box 2760

Date 4-14-80

No. Final Copies 5

Contractor Quarles Drilling Corp. Top Choke 1/4"
Rig No. 1 Bottom Choke 3/8"
Spot 1980'FSL & 1980'FEL Size Hole 8 1/2"
Sec. 1 Size Rat Hole --
Twp. 19 S Size & Wt. D. P. 4 1/2"
Rng. 28 E Size Wt. Pipe --
Field Palmillo Turkey Trk. I. D. of D. C. 2 1/4"
County Eddy Length of D. C. 744'
State New Mexico Total Depth 6700'
Elevation 3403' K.B. Interval Tested 6546-6562'
Formation Bone Springs Type of Test Inflate
Straddle

Flow No. 1 -- Min.
Shut-in No. 1 -- Min.
Flow No. 2 -- Min.
Shut-in No. 2 -- Min.
Flow No. 3 -- Min.
Shut-in No. 3 -- Min.

Bottom
Hole Temp. 180° F
Mud Weight 8.6
Gravity --
Viscosity 28

Tool opened @ --

Outside Recorder

PRD Make Kuster K-3
No. 13081 Cap. 6050 @ 6551'

	Press	Corrected
Initial Hydrostatic	A	--
Final Hydrostatic	K	--
Initial Flow	B	--
Final Initial Flow	C	--
Initial Shut-in	D	--
Second Initial Flow	E	--
Second Final Flow	F	--
Second Shut-in	G	--
Third Initial Flow	H	--
Third Final Flow	I	--
Third Shut-in	J	--

Lynes Dist.: Hobbs, N.M.
Our Tester: R. Casillas
Witnessed By: Mike Waygood

Did Well Flow — Gas no Oil no Water no
RECOVERY IN PIPE:

MISRUN: Could not obtain packer seats.