

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.O.S.	
LAND OFFICE	
OPERATOR	1

JUN 5 1980

O. C. D.

ARTESIA OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-6287

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Yates Petroleum Corporation ✓ 3. Address of Operator 207 South 4th Street - Artesia, NM 88210 4. Location of Well UNIT LETTER F, 2210 FEET FROM THE North LINE AND 2310 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 19S RANGE 24E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3594' GR	7. Unit Agreement Name 8. Farm or Lease Name Irish Hills-Yeso JE State 9. Well No. 2 10. Field and Pool, or Wildcat Penasco Draw SA Yeso (Assoc) 12. County Eddy
---	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 15" hole at 2:00 PM 5-26-80.

TD 350' - Ran 10 joints of 10-3/4" 40# K-55 (378') of casing set at 350'. 1-Texas Pattern guide shoe at 850' and insert float at 312'. Cemented w/350 sacks of Class C 4% CaCl. PD 3:15 AM 5-27-80. Circulated 28 sacks of cement to the surface. WOC 12 hours, cut off and reduced hole to 9 1/2", drilled plug and tested to 600# OK and resumed drilling.

TD 925'- Ran 23 joints of 20# J-55 ST&C 928' of casing set at 925'. 1-Texas Pattern guide shoe at 925' and insert float at 885'. Cemented w/350 sacks of 65-35 Poz, 8#/sack Kolite, 1/4#/sack celloflakes, 3% CaCl. Tailed in w/150 sacks of Class C 2% CaCl. PD 10:15 AM 5-28-80. Cement circulated 50 sacks to surface. WOC 18 hours, NU, reduced hole to 6 1/4", drilled plug, tested to 600# OK and resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine Lombura TITLE Geol. Secty. DATE 6-4-80

APPROVED BY W. A. Gressitt TITLE SUPERVISOR, DISTRICT II DATE JUN 5 1980

CONDITIONS OF APPROVAL, IF ANY: