

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
N.M.O.C.D. COPY
SUBMIT IN TRIPLICATE
(Other Instructions: reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM - 29607

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

BUZZARD FEDERAL

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WILDCAT Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC 17, T20S, R23E

12. COUNTY OR PARISH 13. STATE

EDDY

NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug with logs different from those shown on the well log. Use "APPLICATION FOR PERMIT" for such proposals.)
RECEIVED1. OIL WELL ☐ GAS WELL ☒ OTHER

MAY 27 1980

2. NAME OF OPERATOR

MESA PETROLEUM CO

3. ADDRESS OF OPERATOR

1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

2310' FSL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4252.7' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) 8-5/8" Csg

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 11" hole to 1809' on 5-20-80. Ran 45 jts 8-5/8", 24#, K-55, ST&C casing set at 1808' with FC at 1773'. Cemented with 200 sx Thix-Set + 10# Gilsonite, + 1/2# celloflake, followed by 190 sx Lite + 5# Gilsonite, + 1/4# celloflake, and tailed in with 200 sx "C" + 2% CaCl. Cement did not circulate. Ran temperature survey, TOC at 620'. Set 4 plugs with 250 sx Class "C" + 2% CaCl and 1 plug with 250 sx Thix-Set. Witnessed by Bird Jones, USGS. Tested casing & BOP's to 1500 psi for 30 min. - OK, hydrill to 1000 psi, reduced hole to 7-7/8" and drilled ahead on 5-21-80.

RECEIVED

MAY 28 1980

O. C. D.
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

R. E. Mack

TITLE Regulatory Coordinator

DATE 5-22-80

(This space for Federal or State office use)

APPROVED BY

GEORGE H. STEWART

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side