

N.O.C.D. COPY

Form Approved.  
Budget Bureau No. 42-R1424

C/SF  
File ✓

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐  
2. NAME OF OPERATOR  
Amoco Production Company ✓  
3. ADDRESS OF OPERATOR  
P. O. Box 68 Hobbs, NM 88240  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 660' FNL & 1980' FWL, Sec. 26  
AT TOP PROD. INTERVAL: (Unit C, NE/4, SW/4)  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  
TEST WATER SHUT-OFF ☐ ☒  
FRACTURE TREAT ☐ ☐  
SHOOT OR ACIDIZE ☐ ☐  
REPAIR WELL ☐ ☐  
PULL OR ALTER CASING ☐ ☐  
MULTIPLE COMPLETE ☐ ☐  
CHANGE ZONES ☐ ☐  
ABANDON\* ☐ ☐  
(other) ☐ ☐

5. LEASE  
LC-029392(b)  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
Greenwood Pregrayburg Unit Fed. D Com.  
8. FARM OR LEASE NAME  
Greenwood Pregrayburg Unit Fed. D Com.  
9. WELL NO.  
1  
10. FIELD OR WILDCAT NAME  
Und. Shugart Penn  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
26-18-31  
12. COUNTY OR PARISH 13. STATE  
Eddy NM  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3653.4 GL

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OCT 8 1980

O. C. D.

RECEIVED

SEP 30 1980

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Drilled to a TD of 11875' and ran 701' of 20# 17-80 5-1/2" casing, 9696' of 17# 17-80 and K-55 5-1/2" casing, and 1478' of 15.5# K-55 5-1/2" casing set at 11876'. Cemented with 1325 SX Lite cement with additives and 825 SX Class H cement with additives. Plugged down at 5:00 p.m. 8-26-80. Cement did not circulate. Ran temp survey. Top of cement at approx. 3520'. Will test casing when completion unit is moved in.

0+4-USGS, A 1-Hou 1-Susp 1-LBG 1-W. Stafford, Hou 1-Conoco

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Benton Green TITLE Ast. Adm. Analyst DATE 9-26-80

APPROVED BY R. Chester TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL IF ANY:

ACCEPTED FOR RECORD

(This space for Federal or State office use)

OCT 2 1980

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side