

Form 9-331
Dec. 1973Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR
Amoco Production Company ✓
3. ADDRESS OF OPERATOR
P. O. Box 68 Hobbs, NM 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990' FSL & 1980' FWL, Sec. 3
AT TOP PROD. INTERVAL: (Unit N, SE/4, SW/4)
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☒

☐

☐

☐

☐

☐

☐

☐

5. LEASE
NM-6026
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Federal BV #1
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Und. Morrow
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
3-19-24
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3678.4' GL

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

MAR 17 1981

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled to a TD of 8817' and ran 2821' of 5-1/2" 17# K-55 and 5996' of 5-1/2" 15.5# K-55 casing set at 8817'. Cemented with 1310 SX Trinity Lite with additives and 475 SX Class "H" with additives. Plugged down at 5:50 p.m. 2-19-81. Ran temperature survey and found TCMT approx. 2000'. WOC 18 hrs. and tested casing with 1000# for 30 min. Tested OK. Currently well is shut-in waiting on completion unit.

0+5-USGS, A 1-Hou 1-Susp 1-W. Stafford, Hou 1-Pennzoil 1-GLF
1-HNG 1-Perry 1-Yates, A 1-Read & Stevens 1-Abby Corp. 1-Coquina

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Gerald L Foshee TITLE Admin. Analyst DATE 3-16-81

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
PETER W. CHESTER

MAR 19 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side