

Drawer 00
Artesia, NM 88210
U.S. FED 88210
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THIS MANNER
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
NM-30629

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use APPLICATION FOR PERMIT for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Yates Petroleum Corporation		8. FARM OR LEASE NAME Eastern Shore "QW" Federal	
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1623' FSL & 1693' FEL of Sec. 8-T19S-R27E		10. FIELD AND POOL, OR WILDCAT Wildcat Morrow	
14. PERMIT NO.		15. ELEVATIONS (Show whether DE, RT, GK, etc.) 3334' GR	
		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT	☐	FRACTURE TREATMENT	☒
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☒
REPAIR WELL	☐	(Other) Perforate	☒
(Other)	☐	(X-ent): Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

TD 10158'. WIH w/casing gun on wireline & perforated 9756-9773' as follows: 9756-9759' (6 holes) & 9766-9773' (14 holes) total 20 .50" holes. Set packer at 9720'. Acidized well w/3000 gallons 7-1/2% MS acid & N2 & ball sealers. Frac'd well w/2000 gallons 7-1/2% MS acid followed w/30000 gallons 3% MS acid & 15000 gallons CO₂ & 90000# (10000# 100-mesh & 80000# 20/40) sand.

Well cleaned up and stabilized at 163 psi on 1/2" choke = 1000 mcf/gpd.

RECEIVED
SEP 21 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED: ACCEPTED FOR RECORD
ROGER A. CHAPMAN
(This space for Federal or State office use)

APPROVED BY: SEP 19 1981
CONDITIONS OF APPROVAL, IF ANY:

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

TITLE: Engineering Secretary DATE: 9-17-81

TITLE: DATE:

*See: Instructions on Reverse Side