

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-23890
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Sara AHA Com
8. Well No. 1
9. Pool name or Wildcat South Dagger Draw Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> RE-ENTRY <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION	3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line Section 11 Township 20S Range 24E NMPM Eddy County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3608' GR
---	--	--	---	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Perforate, Squeeze, Swab, Test ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-11-90. Drill out CIBP at 7700'. TIH to 7975'. TOH. Pick up bit and scraper. TIH to 7975'. Circulate hole with 2% KCL water. TOH with bit and scraper.
5-15-90. Perforated 7853-7876' w/7 - .50" holes as follows: 7853, 55, 57, 73, 74, 75 and 7876'. Show of gas on swab.
5-18-90. Squeezed perfs 7853-7876' w/75 sx Class H + .6% Halad 9. Perfs did not squeeze. Pumped 25 sacks Class H + .6% Halad 9. Squeeze perfs to 2000 psi.
5-19-90. TIH w/1 jt tailpipe. Set at 7696' and Guiberson Uni V packer set 7657'.
5-20-90. Swabbed well with good show of gas from old perforations 7754-7766'.
5-23-90. RDPU.
5-24-90 - 6-15-90. Waiting on BLM right-of-way approval and building pipeline.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 6-15-90
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN 26 1990