

c/SF

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other

2. NAME OF OPERATOR

Chama Petroleum Company

3. ADDRESS OF OPERATOR

5447 Glen Lakes Dr., Dallas, Texas 75231

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1650' FNL & 1980' FEL of Sec. 3

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Intermediate casing

5. LEASE

NM-14758

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME RECEIVED

8. FARM OR LEASE NAME
Huber Federal OCT 22 1982

9. WELL NO.

#2

O. C. D.

10. FIELD OR WILDCAT NAME
ARTESIA, OFFICE

Undesignated Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 3, T-20-S, R-25-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3465.2' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-13-82: Drilling at 4550', made 473' in last 24 hrs., drilling at 19' per hr., Pump Pressure 1200, Strokes 92, RPM 60, Wt. on Bit 45,000, M.W. 8.4, Vis. 28, PH 10, survey at 4193' was 1°

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Rathie Craft

TITLE Prod. Secretary

DATE October 14, 1982

APPROVED BY

(ORIG. SGD.) DAVID R. GLASS

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 19 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED

OCT 18 1982

MINERAL RIGHTS SERVICE
ROSWELL, NEW MEXICO

451

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

2. NAME OF OPERATOR
Chama Petroleum Company ✓

3. ADDRESS OF OPERATOR
5447 Glen Lakes Dr., Dallas, Texas 75231

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1650' FNL & 1980' FEL of Sec. 3
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) Intermediate Casing		

5. LEASE

NM-14758

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

RECEIVED

8. FARM OR LEASE NAME
Huber Federal

9. WELL NO.
#2

OCT 22 1982

10. FIELD OR WILDCAT NAME
Undesignated MORTGAGE OFFICE

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 3, T-20-S, R-25-E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3465.2' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-10-82: At 3175' tripping in hole, ran 79 jts. 8 5/8" tubing set at 3175', cemented with 550 sacks Halliburton light & 485 sacks 50-50 poz Class "C", circulated 115 sacks to surface, plugged down at 4:00 P.M., waited on cement 13 hrs.

10-11-82: Drilling at 3573', made 398' in last 24 hrs., drilling at 19' per hr., Pump Pressure 1200, Strokes 92, RPM 60, Wt. on Bit 45,000, M.W. 8.4, Vis. 28, PH 10

10-12-82: Drilling at 4077', made 504' in last 24 hrs., drilling at 20' per hr., Pump Pressure 1200, Strokes 92, RPM 60, Wt. on Bit 45,000, M.W. 8.4, Vis. 28, PH 9.5, survey at 3625' was 1/2°

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE _____ DATE _____

APPROVED BY: (ORIG. SGD.) DAVID R. GLASS
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

OCT 19 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side