Form 9–331	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM-14758
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTSE ON MELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME Huber Federal
1. oil gas well down other OCT 2 6 1982	9. WELL NO.
2. NAME OF OPERATOR O. C. D.	#2 10. FIELD OR WILDCAT MAME
Chama Petroleum Company V ARTESIA, OFFICE 3. ADDRESS OF OPERATOR	Undesignated Morrow
5447 Glen Lakes Dr., Dallas, Texas 75231	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) At Surface: 1650' FNL & 1980' FEL of Sec. 3	<u>Sec. 3, T-20-S, R-25-E</u> <b>12.</b> COUNTY OR PARISH <b>13.</b> STATE
AT TOP PROD. INTERVAL:	Eddy New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3465.2' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
PULL OR ALTER CASING	
CHANGE ZONES	
ABANDON* L L (other) Drilling Activity	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and
10-18-82: Drilling at 5957', made 361' in last Bit #5 has made 954' in 59 1/4 hrs., RPM 60, Wt. on Bit 35,000, M.W. 8.4, was 2 1/2°, Totco at 5839' was 2 1/2°	Pump Pressure 1200, Strokes 92, Vis. 28, PH 10, Totco at 5620'
10-19-82: Drilling at 6373', made 416' in last Bit #5 has made 1370' in 82 hrs., Pum Wt. on Bit 45,000, M.W. 8.4, Vis. 28, Totco at 6336' was 2°	p Pressure 1200, Strokes 92, RPM 60,
10-20-82: Drilling at 6617' in 70% lime & 30% s drilling at 23' per hr., Bit #5 made has made 213' in 11 1/4 hrs., Pump Pr Wt. on Bit 45,000, M.W. 9.2, Vis. 28, Subsurface Safety Valve: Manu. and Type	1387' in 83 hrs., Bit #6 M89 Security essure 1200, Strokes 92, RPM 60,
18. I hereby certify that the foregoing is true and correct	
	DATE
ACCEPTED FOR RECORD is space for Federal or State o	
(ORIG SCD) DAVID'R' CLASS	,
CONDITIONS OF APPROVOCT 25 1982	
U.S. GEOLOGICAL SURVEY	
ROSWELL, NEW MEXICO .See Instructions on Reverse	a Side