

UNITED STATES NM OIL CONS. COMMISSION
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

RECEIVED

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR Chama Petroleum Company

3. ADDRESS OF OPERATOR 5447 Glen Lakes Dr., Dallas, Texas 75231

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1650' FNL & 1980' FEL of Sec. 3
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) Drilling Activity		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-21-82: Drilling at 7220' in 90% sand & 10% lime, made 603' in last 24 hrs., Bit #6 has made 816' in 34 1/2 hrs., Pump Pressure 1200, Strokes 90, RPM 60, Wt. on Bit 45,000, M.W. 9, Vis. 28, PH 10.5, Chlorides 45#, Totco at 7013' was 1 3/4"

10-22-82: Tripping for cracked drill collar at 7744' in 20% shale & 80% lime, made 524' in last 24 hrs., Bit #6 has made 1340' in 56 1/4 hrs., Pump Pressure 1200, Strokes 90, RPM 60, Wt. on Bit 45,000, M.W. 9, Vis. 28, PH 10, Totco at 7510' was 1 3/4"

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Patricia Craft TITLE Prod. Secretary DATE October 22, 1982

ACCEPTED FOR RECORD

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

APPROVED BY _____ DATE _____
CONDITIONS OF APPROVAL OCT 25 1982U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

LEASE
NM-14758
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Huber Federal9. WELL NO.
#210. FIELD OR WILDCAT NAME
Undesignated Morrow11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 3, T-20-S, R-25-E12. COUNTY OR PARISH Eddy
13. STATE New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3465.2' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

OCT 25 1982

OIL & GAS

MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO